

**Centralia High School
Centralia School District 401
Centralia, WA**

Total Score = 69% or "Poor"

Date Scored: April X, 2016

Scorer: Jerry Gee

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, AQ, Acoustics	Other	
Exterior									
Pedestrian Circulation	Y	Fair						x	The entrance used by bus riders is not ADA accessible.
Vehicle Circulation (incl. service vehicles)	Y	Good							
Grounds and Fields	Y	Fair		x		x			The athletic fields are located approximately a mile away from the main school. The high school does have adequate fields for physical education on the school property. There are not any external restrooms.
Parking	Y	Good							
Safety-Security, Signage, Fencing, Etc.	Y	Poor		x		x		x	Line of sight supervision of the front door is not possible due to the location of the office. Many of the doors remain open during the day because the school utilizes a number of portables. The school does not have adequate internal directional signage. The PA system is not consistent throughout the building.

	Program Space Needed?	Assigned Rating	Comment Areas							Comments	
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other			
Administration											
Administrators	Y	Fair	x	x	x					x	The school does not have adequate office space for the secretarial staff. One staff member's desk is located in a hallway.
Reception-Clerical-Business	Y	Good									
Discipline (Security, Detention, ISS, etc.)	Y	Good									
Administrative Support	Y	Fair		x							The conference room is located down the hallway and across the foyer from the main administrative office. It was previously a general classroom and also accommodates an office area.
Student Services											
Counselor, SW Offices	Y	Fair			x						The career center was previously a general classroom. It does not have any built in cabinetry for the storage of supplies and materials.
Clinic and Restroom	Y	Poor	x		x					x	The nurse's clinic is extremely small in size and only accompanies one cot. It is equipped with a restroom, however the restroom is not ADA accessible. The clinic lacks adequate office space.
Student Services Support	Y	Good									
Staff Support											
Staff Workrooms	Y	Good									
Staff Lounge	Y	Good									
Staff Support and Restrooms	Y	Unsatisfactory	x	x		x				x	The school has one set of staff restrooms for the entire building.

	Program Space Needed?	Assigned Rating	Comment Areas							Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other		
Food Services										
Food Preparation	Y	Fair	x							The high school kitchen also prepares all of the food for the elementary schools. The kitchen is small for the number of staff and number of meals prepared daily.
Cafeteria	Y	Fair	x	x					x	The cafeteria is adequate in size for the student body, however a portion of the cafeteria can only be accessed by climbing stairs. The school has only one serving line and it is extremely small.
Dishwashing-Scullery	Y	Good								
Food Storage (Freezer, Cooler, Dry Storage)	Y	Good								
Food Services Support (office, lockers, etc.)	Y	Good								
Custodial-Maintenance										
Custodial - Maintenance	Y	Fair		x	x	x				The school has only two custodial areas. Due to the school having external facilities such as a weight room and wrestling room and numerous portables custodial staff must transport cleaning equipment to these various locations.
Restrooms and Corridors		Poor	x			x				The school does not have an adequate number of student restrooms. None of the student restrooms are ADA compliant
Custodial-Maintenance Support	Y	Good								
General Classrooms	Y	Poor	x		x				x	Due to the school being an open school designed originally the classroom configurations and size differ significantly from room to room. None of the classrooms have any built in cabinetry for storage of supplies and materials. Some of the classrooms do not have natural lighting. Noise infiltration between the instructional spaces is a major issue. The school uses 10 portable classrooms.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Science									
Science Labs	Y	Poor	x			x		x	The science rooms sizes and configurations include a lecture with a separate lab area in the back of the room, and a lecture area with cabinetry and some lab stations located on the perimeter the room. The classroom areas in the rooms are extremely small. The labs have never been renovated since they were built and are in significant need of renovation. The safety showers do not have drains and all of the labs do not have the adequate amount of gas and water due to leaky pipes.
Science Support	Y	Fair				x	x	x	The science facilities have adequately sized preparation rooms. These rooms are not properly ventilated, lack adequate running water and are in need of significant renovation.

DRAFT 5-13-16

Program Space Needed?	Assigned Rating	Comment Areas						Comments
		Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	

Special Needs									
Special Education - Resource	Y	Fair	x		x			x	The resource rooms differ significantly in size. The English language learners room is extremely small and located in what was previously a storage room. None of the resource rooms have adequate storage for supplies and materials. The school does not have any spaces that were designed for small group or individualized instruction.
Special Education - Cognitive	Y	Fair			x			x	The severe and profound special education classroom is equipped with a restroom. The changing table is located in the classroom and is not adjacent to a sink. The room does not have adequate storage for supplies and materials and mobility devices.
Special Education - Behavior	Y	Fair			x	x			The second special education classroom does have a kitchenette for the teaching of life skills. The room does not have a restroom. It does not have adequate built in cabinetry for material and equipment storage.
Title I		Fair		x	x				The Title 1 room is a general classroom space. It does not have any built in cabinetry for material storage. Noise levels from the adjacent classrooms can be an issue.
Psychologist/SLP	Y	Good							
Special Needs Support	Y	Poor	x	x	x	x	x	x	The school does not have adequate office space for special needs staff.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Physical Education									
Gymnasium/Multipurpose	Y	Fair		x	x				The wrestling/yoga room is located in a metal building approximately 30 yards from the main school. The building does not have adequate storage for physical education equipment. The building is not equipped with a restroom.
Weight Room	Y	Poor	x	x	x	x			The weight room is located in a metal building which is approximately 30 yards from the main school building. It is small in size, does not have built in storage, and is not equipped with a restroom. The space is not well ventilated.
Lockers	Y	Fair	x					x	The school has one boys and one girl's locker room. There are not have any visitors locker rooms or team rooms. There are additional locker rooms located adjacent to the football stadium and other athletic fields which are approximately a mile from the school.
Physical Education Support	Y	Fair	x	x					Some of the physical education and coaches offices are located in storage rooms.

	Program Space Needed?	Assigned Rating	Comment Areas							Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other		
Performing Arts										
Music - Instrumental	Y	Fair	x		x					The instrumental room is small in size for the number of students served. There is not adequate storage for instruments and uniforms which are currently stored in practice rooms. The band room is not equipped with a sink.
Music - Vocal	Y	Fair	x							The vocal room is small in size for the number of students served.
Music Support	Y	Fair							x	The music faculty offices are located in practice rooms.
Drama - Stage Auditorium	Y	Fair	x							The stage is two levels. The front level is lower than the back level which significantly restricts the size of the stage and how the stage can be used.
Drama Support	Y	Poor	x		x	x			x	The stage area has one dressing room which was previously a restroom. The school does not have a scene shop, costume storage, green room, or storage for props etc.
Library - Media										
Library	Y	Fair	x					x	x	In order to access the library students must go upstairs to access the main entrance. There are ADA ramps on the backside of the facility. The library has low ceilings, small instructional spaces including a computer lab, and inadequate technology projection equipment. In the center of the library is a pit which is not ADA accessible. The library is small in size for the school population.
Library - Meeting, Conference	Y	Unsatisfactory	x	x	x	x	x	x	x	The library does not have a conference/meeting room.
Library Support	Y	Good								

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Computer Labs									
Computer Labs	Y	Fair	x		x				The computer labs were originally general classrooms. They do not have adequate storage. The computer lab in the science areas require students to stand while using the computers.
Computer Lab Support (MDF, IDF, etc.)	Y	Good							
Visual Arts									
Art - 2D/3D	Y	Fair	x						The ceramics room is small for the number of students served. The kiln is located in the corner of the room which can present a potential safety hazard.
Art - Computer Graphic	N								
Art Support	Y	Good							

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Career Technical Education									
Ag., Natural Resources, etc.	Y	Fair				x		x	The classroom is L-shaped with lab tables making the room extremely difficult to configure.
Ag., Natural Resources, etc. Support	Y	Good							
Business, Finance	Y	Good							
Business, Finance Support	Y	Poor	x		x				The teacher does not have an office other than a desk in the classroom area.
Construction, Architecture	Y	Fair						x	The woodshop does not have adequate electrical power. The electrical circuitry in the woodshop is also tied to the adjacent metals shop which can cause significant power issues. There is not a separate classroom for the shop.
Construction, Architecture Support	Y	Poor	x		x			x	The construction teacher does not have a separate office area.
Engineering	Y	Poor	x		x			x	Robotics are taught in a computer lab that is utilized for web design and yearbook. The robotics area is extremely small with limited storage. The workbenches for robotics are also the computer tables. The hallways are often used for the robots to be tested.
Engineering Support		Poor	x		x				The robotics instructor does not have a separate office area.
Health Science	Y	Poor	x		x	x		x	The school has a sports medicine program that is housed in a general classroom. It does not have a sink or any other built-in specialized equipment for sports medicine. It does not have adequate storage.
Health Science Support	Y	Poor	x		x				The sports medicine instructor does not have an office area other than in the classroom.
Hospitality, Toursim	N								
Hospitality, Toursim Support	N								

	Program Space Needed?	Assigned Rating	Comment Areas						Comments	
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other		
Human Services, Family Consumer Sci.	Y	Fair	x						The family consumer science classroom/kitchen area is extremely small for the number of students served. An additional family consumer science classroom is currently being used to teach physics.	
Human Services, Family Consumer Sci. Support	Y	Poor	x		x			x	The family consumer science instructor does not have an office other than a desk in the classroom.	
Information Technology, Networking	N									
Information Technology, Networking Support	N									
Manufacturing, Metals, etc.	Y	Poor	x	x				x	x	The welding/metal shop is small in size and is extremely difficult to configure. As the shop is currently configured is difficult to supervise. The shop area is in need of renovation. The classroom area is extremely small.
Manufacturing, Metals, etc. Support	Y	Poor	x				x			The metals shop area does not have a locker room or restroom.
Marketing	N									
Marketing Support	N									
Other		Fair					x	x	x	The photography/media area does not have a permanent studio for photography. Connections to the Ethernet are not adequate. The instructor does not have a separate office area. There is not adequate storage for supplies and materials.